STATE OF UTAH NATURAL RESOURCES Oil, Gas & Mining

ACT/0/3/032-874 F. \$3 + 2

Norman H. Bangerter, Governor Dee C. Hansen, Executive Director Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

January 22, 1988

Mr. Andrew C. King Genwal Coal Company P.O. Box 1201 Huntington, Utah 84528

Dear Mr. King:

Re: Review of Conditional Approval Response, PAP Amendment, Proposed Onsite Coal Processing and Truck Loading Facility, Genwal Coal Company, Crandall Canyon Mine, ACT/015/032-87A, Folder #2, Emery County, Utah

The Division has completed its review of the revised plates, received November 16, and December 9, 1987 respectively, for the proposed onsite coal crushing/screening and truck loadout facility. The supplemental information is insufficient to address the conditions which were outlined in the Division's August 21, 1987 conditional approval letter. Please refer to the attached technical memorandum for an explanation of the information which must be provided prior to final Division approval of the proposed amendment.

The United States Forest Service (USFS) has informed the Division that Genwal has failed to address previous concerns as outlined in their July 27, 1987 letter to the operator. The USFS concerns must also be resolved before the operator may commence construction related to this permit amendment.

If possible, please provide a response to all of the condition(s) and comments attached to this letter by February 22, 1988. Also, please ensure that the response is formatted in a manner to allow direct insertion into the approved permit application package (PAP). Thank you for your cooperation in completing this permitting action.

Sincerely,

D. Wayne Hedberg

Data Management Coordinator

jr Attachment

cc: P. Rutledge

P. Rutledge R. Hagen L. Braxton

G. Morris

R. Harden S. Linner

D. Parker

P.F.O.

January 4, 1988

TO:

File

FROM:

Randy Harden, Reclamation Engineer

RE:

Proposed On-Site Loadout Facility, Crandall Canyon Mine,

Genwal Coal Company, ACT/Ol5/O32, Emery County, Utah

## Summary:

The operator has sent revised plates to the Division in its request to include a loadout facility as part of the permit area operations. The operator has also included letters of this request to the Department of Air Quality and the United States Forest Service.

The information submitted by the operator is not considered to be complete. The operator has not provided suitable text and descriptive information of the proposed facilities; has not submitted such information in a manner which can suitably be inserted into the plan; and has not provided plans and designs for the construction, maintenance, and reclamation of the facilities.

## Body:

Maps submitted by the operator are generally considered to be adequate for the proposed loadout facility. The operator needs to describe the loadout facility as required in UMC 784.11 through UMC 784.16, UMC 784.24, UMC 784.26 and UMC 800, and incorporate that information into the text of the MRP, in order to consider the proposal complete and in accordance with Subchapter K of the Regulations.

Bonding calculations for the reclamation of the proposed facilities must also be included with the proposal. The addition of the loadout may result in a modification of the bonding requirements for Genwal.

Page 2 ACT/015/032 January 4, 1988

Until such time as the information regarding the description of the loadout facility is provided by Genwal to the Division, this proposal cannot be accepted. Additionally, incorporation of the loadout facility will also be dependent on stipulations or other requirements of the Department of Air Quality and the Forest Service.

jr
cc: J. Leatherwood
 S. Linner
1384R/12:13